

BV-AVON 2 MANDAY FACTORY AUDIT CHECKLIST WITH (AVON INTERNATIONAL)

BUREAU VERITAS PROPRIETARY - copyright Bureau Veritas [2004] DO NOT DISCLOSE OUTSIDE YOUR ORGANISATION WITHOUT BUREAU VERITAS PRIOR WRITTEN CONSENT.

Performance Overview				
Audit Details				
BV Ref:	10180661528			
Auditor:	MONICA MIAO			
Audit Date:	Mar 30, 2018			
Date of Previous Audit:	Apr 07, 2017			
Previous Audit #:	10170390375			
Vendor Name:	THE HOUSE OF BUSBY	THE HOUSE OF BUSBY		
Factory Name:	JIAXING JIAXIDA LEATHER C	JIAXING JIAXIDA LEATHER CO LTD		
Address:	NO.193 YUANFENG ROAD XI	NO.193 YUANFENG ROAD XIUZHOU DISTRICT JIAXING		
E-Mail Address:	XLF@LAYOGROUP.COM			
Tel:	86-573-82076819	Fax: 86-573-89977444		
Country:	CHINA			
Scope of Audit				
BV-Avon Factory Assessment Protocol – 2 MD				
Audit Category				

Audit Category

Women's Handbags

Key Personnel					
Present at Audit (please tick 'X' below)					
Name	Job Title	Opening Meeting	On-site Audit	Documentation Review	Closing Meeting
Mr. Wang Ji	General Manager				Х
Mr. Wang Ji	Production manager	х		X	Х
Mr. Zhou Guoliang	Quality supervisor	х	x	Х	Х
Ms. Li Ling	Sales	Х	Х	Х	Х

Audit Results					
Non Conformance(s)				Risk Level for	Follow-up
Level to Standard	Critical(s)	Major(s)	Minor(s)	Supply	frequency
96.02%	0	0	17	YELLOW	12 MONTHLY FOLLOW-UP

Company Profile

-Factory established: Jan.2015

- ~Main manufacturing processes: Cutting, Gluing, Assembly, Sewing, Finishing and Packing
- ~Product category: Women's Handbags
- ~Factory area: 2,000 square meter
- ~Employee number: 42 employees
- ~Production capacity: 50,000 pcs per month
- ~International certification: Nil
- ~Peak season: Not obvious
- ~Major market: Africa (70%), South American (20%), Europe (10%)
- ~Major customer: Avon (70%), Primark (20%)
- ~Product liability insurance and product recall insurance were purchased? Nil
- ~Integrity and bribery case: No

Remark i): (if any) Sand blasting is not a current capability at the factory and never was.



Analysis of Site Compliance

Degree of compliance Overview (per section)

Section	Green	Yellow	Orange	Red	N/A	Total Questions
1. Quality Management Standard	42 (80.77%)	6 (11.54%)	0 (0.00%)	0 (0.00%)	4 (7.69%)	52
2. Good Manufacturing Practice (Gmp)	39 (81.25%)	9 (18.75%)	0 (0.00%)	0 (0.00%)	0 (0.00%)	48
3. Product Control	32 (88.89%)	1 (2.78%)	0 (0.00%)	0 (0.00%)	3 (8.33%)	36
4. Process Control	28 (82.35%)	1 (2.94%)	0 (0.00%)	0 (0.00%)	5 (14.71%)	34
OVERALL	141 (82.94%)	17 (10.00%)	0 (0.00%)	0 (0.00%)	12 (7.06%)	170 (100%)

Audit Findings Summary Critical Non-conformance Section					
Clause Clause Requirement Levels of Non- Audit Findings No. Conformance Conformance					
	ause Requirement	ause Requirement Levels of Non-			

	Audit Findings Summary					
Clause No.	Clause Requirement	Levels of Non- Conformance	Audit Findings			
1	QUALITY MANAGEMENT STANDARD					
1.3.1	The company shall ensure that mechanisms (e.g., appraisal, KPI) are in place to monitor the effectiveness of employees' operation.		Appraisal Mechanisms was established to monitor the effectiveness of employees' operation, but the monitoring records were only maintained for management instead of all employees.			
1.9.2	Raw materials (including packaging), work in progress and finished products shall be identified to ensure traceability.		Per factory tour, most raw materials, semi-finished products were properly identified, but some incoming sewing threads and zippers were not properly identified with incoming date, PO#/lot#, quantity, etc. for traceability.			
1.9.5	The system shall be regularly tested to ensure traceability can be determined from raw material source to finished product and vice-versa.	(VELLOW)	During this audit, traceability testing records were maintained for review, but the procedure for testing of traceability system showing defined interval was not established.			
1.10.2	The company shall establish procedures to ensure that customers are notified immediately should an incident take place, which has potentially resulted in an illegal or unsafe product that has been delivered to the customer.	(YELLOW)	The factory established a procedure that to notify customer immediately if any incident take place, but there was no time frame (such as 24 hours) was defined accordingly.			
1.13.2	Where the employee carries out procedures critical for product safety, legality and quality the company shall have full training records.		Per document review and employees interview, the training program for employees carries out procedures critical for product safety, legality and quality was performed in the factory, but per reviewing the training records, it was noted that the effectiveness evaluation was only performed for part of trainee instead of all.			
1.15.5	All documents in use are the correct version.	Minor (YELLOW)	Per factory tour, one work instruction provided at gluing area was not issued with version number and document number.			
2	GOOD MANUFACTURING PRACTICE (GMP)					
2.3.1	Premises are sufficiently illuminated in order to permit effective cleaning, production, monitoring, and inspection.	Minor (YELLOW)	By lux meter checking during factory tour, lighting conditions for incoming inspection area (510lux) and finished products inspection area (848 lux) were insufficient (Below 1000 lux).			
2.4.2	The company shall establish maintenance program to ensure all equipment and production machinery are adequately maintained.	Minor (YELLOW)	Machine maintenance program was established and performed in the factory, and relevant maintenance records were maintained for review. But per factory tour, some sewing machine was not clean.			
2.5.1	Cleaning practices shall be completed so as to minimise risk of contamination.	Minor (YELLOW)	The factory conducted 5S management system in the factory, cleaning schedule & records were provided for review, but some trashes were found on floor of die-cutting area.			
2.6.3	No evidence of employee wearing jewellery, watches, other potentially contaminating apparel (check company's policy) observed.	Minor (YELLOW)	Company's control policy for employee jewelry, watch and other apparel control was established, but it observed that some employees were still wearing jewelery and watches, etc. at finishing and packaging area.			
2.7.1	The company shall either contract the services of a competent pest control organisation, or shall have trained personnel, for the regular inspection and treatment of premises to deter and eradicate infestation. Where the services of a pest control contractor are employed, the	(YELLOW)	Pest control procedure was established, and pest check records were maintained. But per factory tour, the mouse trap equipped in the gluing workshop was not in working condition. Moreover, the distribution map of pest control facility equipped was not established.			

	service contract shall be clearly defined and reflect the activities of the site.		
2.7.3	Pest activity report with corrective actions shall be completed and satisfactorily verified.	Minor (YELLOW)	No pest activity report with corrective actions was completed and satisfactorily verified.
2.8.1	Where there is a risk of contamination, light bulbs and strip lights, including those on electric fly killer units, shall be protected by shatterproof plastic diffusers or sleeve covers or product adequately protected.	(YELLOW)	Per factory tour observation, light bulbs & stripe lights installed at materials warehouse & packing area were protected to against breakage, but light bulbs installed at gluing & oil coating area were not protected, also the products under those lights were not protected
2.8.2	Where there is a risk of contamination, glass windows shall be protected against breakage or product adequately protected.		All glass windows in the factory were not protected and some panels were stored near the glass windows without any protection which may cause contamination.
2.10.1	A waste disposal program shall be established for the collection, collation, and disposal of waste material.		Documented procedure (JXD-EHS-09) was established for waste material control, but no records for the collection, collation, and disposal of waste material were provided for review.
3	PRODUCT CONTROL		
3.5.1	Procedures shall be in place to prevent the contamination of raw materials, packaging and finished products.		Witten procedure was established to protect the materials, semi-products and final goods during carrying and storage, etc. Per factory tour observation, most of materials, semi-products and final goods were well stored, but some cutting panels in light color were stored with protective cover, and some finished products were turned over.
4	PROCESS CONTROL		
4.2.2	Incoming materials, including sub-contracted semi-finished parts / components, shall be inspected/tested against purchase order or specification requirements before use.		Incoming inspection procedure was established for all raw materials, and relevant inspection records were maintained for review. But it was noted that the defect description was not recorded in some inspection records for tracing.

Digital Photo Records











